

completed. If the project includes provision of services please indicate the type of service, personnel costs and level or quantity of service to be provided with project funds.

- 2. Project/Activity Budget. Please enclose a complete detailed budget of the entire project. Indicate (in **bold**) specific items of requested MSFT funding including (where applicable) a schedule and priority of project items to be considered if the project is funded at a reduced level. Were other, less costly, approaches considered when preparing the budget for the project? Are there elements that could be eliminated or deferred if funding is not available for the entire project?
- 3. **Project Assessment.** Describe how the effectiveness of the project will be assessed and measures that will be used to determine if it has attained its objectives. Please note a report will be due at the end of the semester (or fiscal year for annual projects). If funded, how will the project acknowledge the use of student funds so that students are aware that their student fees made (or helped to make) it possible? If appropriate, indicate how the project or activity promotes sustainability at CI.
- 4. Sources of Project Support. Please list the other sources of funding, and additional support for the activity. If this project or activity has been conducted previously please indicate how it was funded. Please explain if MSFT is the only source of support for the project.

**Fiscal Management:** Project sponsor's unit or department may be responsible for incurred over and above what is funded through the MSFT. If support is requested for costs beyond initial award, or for use on activities or materials not included in approved proposals, the project sponsor must seek approval from the MSFT committee. The project sponsor will be responsible for managing purchases and transfers of funds related to approved projects.

Please review MSFT web page for information about the fund and its objectives before submitting your application.



## 1/5/2015

To: MSFT Committee

Ref: Interior Refresh Program - Bell Tower Second Floor Classrooms

Dear Colleagues;

The information to follow describes the areas identified to be included in the interior refresh program for the Bell Tower Core. The scope involved primarily consists of removing and replacing carpet, vinyl baseboard replacement, patching and painting the walls (to the new standard color "Cottage White"), replacing damaged window screens, replacing damaged mini blinds with new roller shades, installation of chair rails to prevent future wall damage and refinishing classroom doors.

These finishes are over 14 years old and are at the end of their useful life cycle. We started refreshing classrooms on the second floor of the Bell Tower Core and are requesting funding to continue on with this effort by refreshing rooms 2515 through 2716. These improvements will dramatically improve the learning environment for our students by providing a more comfortable atmosphere while eliminating the deterioration to our interior finishes which ultimately protect the structure of the buildings.

Here is an example of a typical before and after classroom refresh:



The below examples show the current state of classroom finishes – entrance doors are in need of refinishing, there is stained and worn carpet throughout; walls finishes are failing, damages have occurred due to the need of chair rail and window screen material has pulled away from the majority of the frames allowing insects to enter the spaces.

Prepared By: Guy Spevak, Operations Project Manager for Facilities Services

Page 1





Prepared By: Guy Spevak, Operations Project Manager for Facilities Services

Page 2



The needs for each room are listed below along with an estimate for the repair; please see the attached estimate sheet for a break down of all unit costs.



#### **BT2704**





# Priority 1

Replace carpet, patch / paint, replace damaged window screens and roller shades, and refinish door.

## ESTIMATE: \$13,543.78

### **Priority** 1

Replace carpet, patch / paint, replace damaged window screens, replace roller shades, refinish door and install chair rails.

## ESTIMATE: \$12,056.06



Replace carpet, patch / paint, replace damaged window screens and roller shades, and refinish door.

## ESTIMATE: \$11,778.20

Prepared By: Guy Spevak, Operations Project Manager for Facilities Services

Page 3



# BT 2515



# Priority 2

Replace carpet, patch / paint, replace damaged window screens, replace roller shades, refinish door and install chair rails.

# ESTIMATE: \$18,865.24



# Priority 2

Replace carpet, patch / paint, replace damaged window screens, refinish door and install chair rails.

# ESTIMATE: \$10,830.29



Channel Islands

**DIVISION OF BUSINESS & FINANCIAL AFFAIRS** 

BT 2582



BT 2598





Replace carpet, patch / paint, refinish door, and replace damaged window screens.

## ESTIMATE: \$13,432.87

riority.

Replace carpet, patch / paint, refinish door, and replace damaged window screens.

ESTIMATE: \$13,148.91

The total estimate for this project is \$93,655.35 with an approximate duration of 5 days per room. We would plan to publicize these improvements along with the funding source on our blog, the FS newsletter and post project boards with pertinent information in the hallways adjacent the classrooms being refreshed. This proposal has been built so that the committee can easily remove scope and deduct items as desired.

Please feel free to contact me with any questions or concerns. We thank you for your time and consideration.

Thank you,

REFRESH	
Z	
0	
0	
2	
S	
5	
CL	
02	
0	
0	
) FLO(	
0	
Z	
2	
2	
N	
2	
2	
_	
BELL	
60	
1	
L	
S	
S	

						BELL TOWER 2684 ED TECH I	D TECH I	「「「「「「「「」」」」			
	CAF	CARPET (SF)	PAINT	-	ROLLER SHADES	WINDOW SCREENS	REFINISH DOOR	CHAIR RAIL	SPECIAL WORK	Ĺ	TOTAI
QUANTITY		809	1365		7	9	1	0			
MATERIAL PER UNIT	ş	3.00	Ş	0.50	\$ 400.00	\$ 15.00	\$ 25.00	\$ 3.00			
LABOR PER UNIT	ŝ	4.00	Ş	2.50	\$ 60.00	\$ 60.00	s	5			
MATERIAL COST	ŝ	2,427.00	ŝ	682.63	\$ 2,800.00	\$ 90.00	\$ 25.00	- -		~	6.074.63
LABOR COST	Ş	3,236.00	\$ 3,413.15	.15	\$ 420.00	\$ 360.00	\$ 90.00				7 519 15
TOTAL	ŝ	5,663.00	\$ 4,095.78	.78	\$ 3,220.00	\$ 450.00 \$	\$ 115.00	- \$		* *	13 543 78
										+	

CARPET 655	ft)							
655		PAINT	ROLLER SHADES	WINDOW SCREENS	REFINISH DOOR	CHAIR RAIL	SPECIAL WORK	TOTAI
	_	1228	3	2	1	e		
MALERIAL PER UNIT   \$ 3.0	3.00 \$	0:50	\$ 960.00	\$ 15.00	\$ 25.00	\$ 3.00		
LABOR PER UNIT \$ 4.0	4.00 \$	2.50	\$ 60.00	\$ 60.00	\$ 90.00	\$ 3.00		
MATERIAL COST \$ 1,965.00	\$ 00.	614.23	\$ 2,880.00	\$ 30.00	Ş	\$ 23		¢ 5 744 57
LABOR COST \$ 2,620.00	s	3,071.16	\$ 180.00	\$ 120.00	- ~ ~			C.41.0 2
TOTAL \$ 4,585.00	s	3,685.39	\$ 3,060.00	S	\$ 115.00	\$ 460.67		5 12 056 05
								****

				BELL TOWER 2716 ED TECH II	D TECH II			
	CARPET (SF)	PAINT	ROLLER SHADES	WINDOW SCREENS	REFINISH DOOR	CHAIR RAII	SPECIAL WORK	TOTAL
QUANTITY	666	1239	3	m	1	0	JI FORF MOUN	10121
MATERIAL PER UNIT	\$ 3.00	ş	0.50 \$ 960.00	\$ 15.00	\$ 25.00	\$ 3.00		
LABOR PER UNIT	\$ 4.00	\$	2.50 \$ 60.00	\$ 60.00	Ş	\$ 3.00		
MATERIAL COST	\$ 1,998.00	\$ 619.37	37 \$ 2,880.00	\$ 45.00	S			¢ 5 57 37
LABOR COST	\$ 2,664.00	\$ 3,096.84	84 \$ 180.00	\$ 1	s.			NO 010 2
TOTAL	\$ 4,662.00	\$ 3,716.20	20 \$ 3,060.00	\$		, ,		\$ 11 778 20

	TOTAI				\$ 8.068.29	\$ 10.796.95	\$ 18.865.24	
	SPECIAL WORK							
	CHAIR RAIL	ε	\$ 3.00	\$ 3.00	\$ 324.62	\$ 324.62	\$ 649.25	A contraction of the second se
s CR	REFINISH DOOR	2	\$ 25.00	\$ 200.00	\$ 50.00	\$ 400.00	\$ 450.00	
BELL TOWER 2515 CR	WINDOW SCREENS	e	5 15.00	60.00	45.00	\$ 180.00	\$ 225.00	
	ROLLER SHADES	3	\$ 960.00	\$ 120.00	\$ 2,880.00	\$ 360.00	3,240.00	
	PAINT	1731	\$ 0.50	\$ 2.50	\$ 865.67	\$ 4,328.33	\$ 5,193.99	
	CARPET (SF)	1301	\$ 3.00	\$ 4.00	\$ 3,903.00	\$ 5,204.00	\$ 9,107.00	
		QUANTITY	MATERIAL PER UNIT	LABOR PER UNIT	MATERIAL COST	LABOR COST	TOTAL	

					BELL IOWER 2688 CR	8 CR				
	CARPET (SF)	(SF)	PAINT	ROLLER SHADES	WINDOW SCREENS	REFINISH DOOR	CHAIR RAII	SPECIAL MORK	TOTAI	Г
QUANTITY	812		1368	0	4		e		10101	Т
MATERIAL PER UNIT	\$ 3	\$ 00.	0.50	\$ 960.00	\$ 15.00	\$ 25.00	\$ 3.00			Т
LABOR PER UNIT	\$ 4	\$ 00.	2.50	\$ 60.00	\$ 60.00	\$ 90.00	\$ 3.00			Т
MATERIAL COST	\$ 2,436.00	:00 \$	683.89	\$	\$ 60.00	\$ 50.00	\$ 756.46		¢ 3.486.36	36
LABOR COST	\$ 3,248.00	.00 \$	3,419.47	, ,	\$ 240.00	Ś 1	\$ 256.46		\$ 7 343 93	n g
TOTAL	\$ 5,684.00	.00 \$	4,103.37	\$	\$ 300.00	\$	\$ 512.92		\$ 10.830.79	5 5
									incontan t	

	SPECIAL WORK				10 100 F	2 4,300.38	\$ 9.175.89	73 CEV 2 23 23 87
	CHAIR RAIL S		3.00	3.00		-		
LA	REFINISH DOOR	2	\$ 25.00	\$ 200.00	5000	,	\$ 400.00	Ş
DELL LOWER 206 LA	WINDOW SCREENS	2	\$ 15.00	\$ 60.00	00 UE	20000	\$ 120.00	\$ 150.00
	ROLLER SHADES	0	400.00	60.00			•	
	PAINT	1620	\$ 0.50 \$	\$ 2.50 \$	\$ 809.98 \$		\$ 4,049.89 \$	\$ 4,859.87 \$
	CARPET (SF)	1139	\$ 3.00	\$ 4.00	\$ 3,417.00		4,556.00	\$ 7,973.00
		QUANTITY	MATERIAL PER UNIT	LABOR PER UNIT	MATERIAL COST	ADOR COCT	LABUR LUSI	TOTAL

				BELL TOWER 2598 CR	B CR			
	CARPET (SF)	PAINT	ROLLER SHADES	WINDOW SCREENS REFINISH DOOR	REFINISH DOOR	CHAIR RAIL	SPECIAL MICHY	TOTAL
QUANTITY	1132	1615	0	2	2	0		10.01
MATERIAL PER UNIT	\$ 3.00	) \$ 0.50	\$ 960.00	\$ 15.00	\$ 25.00	\$ 3.00		
LABOR PER UNIT	\$ 4.00	) \$ 2.50	\$ 60.00	\$ 60.00	Ş			
MATERIAL COST	\$ 3,396.00	\$ 807.48	- \$	\$ 30.00	S	\$		¢ 1 382 AB
LABOR COST	\$ 4,528.00	\$ 4,037.42	\$	\$ 120.00	\$ 1			\$ 865.47
TOTAL	\$ 7,924.00	\$ 4,844.91	, ,	\$ 150.00	\$			\$ 13,148,91
							and a second sec	- non - lan

37,481.67	56,173.68	93,655.35	
Material \$	Labor \$	GRAND TOTAL \$	

						and the second se			
TOTALS	CARPET (SF)	PAINT	ROLLER SHADES	WINDOW SCREENS	REFINISH DOOR	CHAIR RAIL	SPECIAL WORK		
UANTITY	6514	10167	16	22	II	σ			
IATERIAL PER UNIT	\$ 3.00	\$ 0.50	\$ 400.00	\$ 15.00	\$ 25.00	\$ 3.00			
LABOR PER UNIT	\$ 4.00	\$ 2.50	\$ 60.00	\$ 60.00	00.0e \$	\$			
AATERIAL COST	\$ 19,542.00	\$ 5,083.25	\$ 11,440.00	\$ 330.00	\$ 275.00	\$ 811.47	~	•	C) 101 CC
ABOR COST	\$ 26,056.00	\$ 25,416.26	\$ 1,140.00	\$ 1.	\$ 1 430 00	\$ 811 A7		~ L	/0.104//0
-	\$ 45,598.00	\$ 30,499.51	\$ 12,580.00	Ş	\$ 1.705.00	\$ 1 677 84		n 1	50,L/3.08
					22122-1-	+ + + + + + + + + + + + + + + + + + +	•	ĥ	CC.CC0,CC

TOTAL	37,378.05	29,695.53	26,581.78	93,655,35
	÷	\$	\$	ŝ
	PRIORITY 1	PRIORITY 2	PRIORITY 3	